

William Lee House
1901 Market Street
Wilmington, Delaware

HABS No. Del- 31 ✓

HABS
DEL.

2- WILM

18

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA
District of Delaware

ADDENDUM
FOLLOWS...

Historic American Buildings Survey
Weston H. Blake, District Officer
909 West Street, Wilmington, Delaware

HABS
DEL.

2. WILM

18-

WILLIAM LEA HOUSE
Wilmington, New Castle County, Delaware

Owner: Armstrong and Pierce, Inc. (RealEstate)

Date of Erection: Early 19th Century

Builder: William Lea


Present Condition: Fair; interior altered and made into small apartments. Exterior changes not in character with original building, such as removal of original sash and poorly proportioned continuous dormer.

Number of Stories: Two and one half with basement.

Materials of Construction: Stone walls and foundations.
Present roof slate. Usual interior frame construction.

Other Existing Records: Offices of Recorder of Deeds and Register of Wills of New Castle County.

Additional Data: Typical example of New Castle County local stone construction. Note the unbalanced treatment of the main facade, with the entrance to one side of the center axis of the building.


District Officer

Rev. Jan. 27.31, THW

Addendum to:
William Lea House
1901 North Market Street
Wilmington
New Castle County
Delaware

HABS No. DE-31

HABS
DEL,
2 - WILM,
18 -

PHOTOGRAPHS

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106